Message-ID:
Date: Wed, 9-Jan-85 05:22:43 EST
Article-I.D.: brl-tgr.7135
Posted: Wed Jan 9 05:22:43 1985
Date-Received: Sat, 12-Jan-85 01:46:08 EST
Sender: news@brl-tgr.ARPA
Organization: Ballistic Research Lab
Lines: 13

    Does anyone have some experience with 8" controllers for
Apple II's? Mine seems to have died after a week's use.

    (a) Who repairs the things, now that Vista is out of business?
    (b) Are there better controllers that will work with Apple CPM?
    (c) Is there anyone with the right setup who would be willing
to transfer a single file from 8" (DSDD) to 5"?

    Any help would be really appreciated...

                          Lance