
Subject: TI 99/4A Screen Death
Posted by [Anonymous](#) on Thu, 02 Apr 1987 16:41:18 GMT
[View Forum Message](#) <> [Reply to Message](#)

Originally posted by: tcamp@ecsvax.UUCP

Article-I.D.: ecsvox.2854
Posted: Thu Apr 2 11:41:18 1987
Date-Received: Sat, 4-Apr-87 15:43:54 EST
Organization: UNC Educational Computing Service
Lines: 15

I purchased an inexpensive TI 99/4a only to plug it in and find that it doesn't work. The t.v. screen does clear (to a sort of murky white), but nothing happens. (a) I've checked the power supply and it's voltage output is o.k. (b) I've tried two different RF connectors, and neither change the situation. (c) I have pulled the back off and cleaned the cartridge port with an eraser.

I note that the speech synthesizer port is a gaping hole. Is there supposed to be some sort of null connector in there when a speech synthesizer isn't hooked up. Could this account for the problem?

I'll appreciate any suggestions.