
Subject: re Pro 8 ROM, Kaypro
Posted by [garey](#) on Tue, 24 Sep 2013 18:12:49 GMT
[View Forum Message](#) <> [Reply to Message](#)

Message-ID:
Date: Sun, 10-Mar-85 10:17:32 EST
Article-I.D.: brl-tgr.9107
Posted: Sun Mar 10 10:17:32 1985
Date-Received: Tue, 12-Mar-85 21:38:51 EST
Sender: news@brl-tgr.ARPA
Lines: 16

The problem is Plu-Perfect is a replacement bios. You probably had the version for the II. The pro-8 rom requires a Kaypro IV BIOS to work properly, I know, because I've been running the Pro 8 rom since it came out. It may or may not work with single sided disks with a II bios, but certainly will not run with double sided disk drives and a kaypro II bios. The problem with your REMEX drives may well be that you were trying to run double sided drives with a bios set up for single sided drives.

Find someone with a Kaypro IV and get them to sysgen a disk for you. also get their "Kaypro IV" version of sysgen and config.com, because the "Kaypro II" versions of these utilities don't work properly on "IV" disks.

As for the Plu-Perfect stuff, you'll have to contact them about getting the Kaypro IV version.

Good Luck Jim Garey garey@ut-ngp