Subject: Question on serial printer flow control Posted by set on Thu, 23 Jan 1986 22:26:19 GMT

View Forum Message <> Reply to Message

Article-I.D.: abic.724

Posted: Thu Jan 23 17:26:19 1986

Date-Received: Sat, 25-Jan-86 07:39:52 EST

Organization: Allen-Bradley Co., Highland Heights, OH 44143

Lines: 15

I've been having problems trying to run my TI-820 serial printer on my Amiga. At 300 baud everything is fine but at 1200 I eventually get a buffer overflow condition. I have tried a few cable arrangements trying to get the TI to toggle CTS, etc but to no effect. I also tried to have the TI send XON/XOFF but that didn't work either. The TI does work at full speed on my old CP/M system. Without knowledge of the serial driver, I'm stuck. Anyone got some ideas? My dealer hasn't been any help after two weeks.

Scott Townsend @ Allen-Bradley Company Industrial Computer Division 747 Alpha Drive, Highland Heights, OH 44143 ...!{decvax,masscomp,pyramid,cwruecmp}!abic!set