
Subject: Question on serial printer flow control
Posted by [set](#) on Thu, 23 Jan 1986 22:26:19 GMT
[View Forum Message](#) <> [Reply to Message](#)

Article-I.D.: abic.724
Posted: Thu Jan 23 17:26:19 1986
Date-Received: Sat, 25-Jan-86 07:39:52 EST
Organization: Allen-Bradley Co., Highland Heights, OH 44143
Lines: 15

I've been having problems trying to run my TI-820 serial printer on my Amiga. At 300 baud everything is fine but at 1200 I eventually get a buffer overflow condition. I have tried a few cable arrangements trying to get the TI to toggle CTS, etc but to no effect. I also tried to have the TI send XON/XOFF but that didn't work either. The TI does work at full speed on my old CP/M system. Without knowledge of the serial driver, I'm stuck. Anyone got some ideas? My dealer hasn't been any help after two weeks.

Scott Townsend @ Allen-Bradley Company
Industrial Computer Division
747 Alpha Drive, Highland Heights, OH 44143
...!{decvax,masscomp,pyramid,cwruecmp}!abic!set